

LABOR AND MATERIALS

1 Copper Lead	Connection $\frac{3}{4}$		\$ 1.31
1 Curb	{ Cock Valve F. S. & V. } $\frac{3}{4}$ in.		\$ 1.75
1 Service Box Old - returned	{ Short $3\frac{1}{2} \times 4\frac{1}{2}$ Long $4\frac{1}{2} \times 5\frac{1}{2}$ Buff. or Rdway }		\$ 1.60
9 Ft. $\frac{3}{4}$ in.	{ Copper Galv Iron Cast Iron } Pipe at 18		\$ 1.62
Nipples	in. at	\$	
Bushings	to in. at	\$	
Red'g Inc'g	{ Couplings to in. at	\$	
Union	in. at	\$	
Meter	in. at	\$	
Lead Joints	at	\$	
Leadite Joints	at	\$	
Hrs. Foreman	at	\$	
Hrs. Chauffeur	at	\$	
$\frac{1}{4}$ Hrs. Tapper	at $6\frac{1}{2}$	\$.16
$3\frac{1}{2}$ Hrs. Labor	at 45	\$	1.58
Hrs. Labor	at	\$	
Hrs. Compressor	at	\$	
Compensation Ins.		\$.06
Trucking		\$	1.00
Builders Use of Water	no patch	\$	
Tap by Messrs	Before P.	\$	
		\$	
		\$	
		\$	
		\$	
		\$	
		\$	9.08

47 - - 1940

St.

Pl.

Ave. No.

Name of Owner

Frank Thomas ^{Est.} Lot South Side Staple

Labor and Mat'l. Report

11110

1940

10

● Curb Box

6 Main

Elev. of Main at tap. 91

Gate at ●

● Gate at

● Curb Box

← 75'0" →