

LABOR AND MATERIALS

1	Copper	Connection		\$
1	Curb	Cock Valve T-S-&V.	in.	\$
1	Service box	Short 3-1/2 x 4-1/2		\$
	Old returned	Long 4-1/2 x 5-1/2		\$
10	Ft.	3/4 in. Copper est.	Pipe at	\$
	Nipples		in. at	\$
	Bushings		to in. at	\$
	Red'g			\$
	Inc'g			\$
	Union		in. at	\$
	Meter		in. at	\$
				\$
	Compound Joints at			\$
	Maintenance Foreman			\$
	Hrs. Water Maint. Man - 1 at			\$
	Hrs. Water Maint. Man - 2 at			\$
	Hrs. Garage Foreman		at	\$
	Hrs. Labor		at	\$
	Hrs. Compressor at			\$
				\$
	Trucking			\$
	Pav't Patch			\$
				\$
				\$
				\$
				\$

St. FOURTH
 No. 7

Name of Owner _____
 TAX ID # 309.12-13-29

Labor and Mat'l. Report 1934, OCT. 12



17-2 28-4

● Curb Box

6" Main Elev. of Main at tap 4 1/2'

Gate at ● ● Gate at

10' to main

3/4" Copper ● Curb Box

OLD SHUT OFF AT MAIN

CELESTA KINGSLEY