LABOR AND MATERIALS

1	Copper / Lead Connection	3/4	$ 1.31
1	Curb Cock / ~~Valve~~ / ~~T. S. & V.~~	3/4 in.	$ 1.75
1	Service Box / ~~Old returned~~ Short 3½x4½ / ~~Long 4½x5½~~ / ~~Buff. or Rdway~~		$ 1.60
25	Ft. 3/4 in. Copper / ~~Galv Iron~~ / ~~Cast Iron~~ Pipe at 18		$ 4.50
	Nipples in. at		$
	Bushings to in. at		$
	Red'g / Inc'g Couplings to in. at		$
	Union in. at		$
	Meter in. at		$
	Lead Joints at		$
	Leadite Joints at		$
	Hrs. Foreman at		$
	Hrs. Chauffeur at		$
7/10	Hrs. Tapper at	62½	$ .44
	Hrs. Labor at		$
9	Hrs. Labor at	45	$ 4.05
	Hrs. Compressor at		$
	Compensation Ins.		$ .14
	Trucking		$ 1.—
	Builders Use of Water	no patch Ext	$ —
			$
			$
			$
			$
			$ 14.79

8 5 - - 1940

St. ~~Pl.~~ Ave. No. 77

Fourth (Lot)

Name of Owner

Edw. Ball

Labor and Mat'l. Report July 16 1940

Tap in center of 60 ft lot.

165' - 7" west of #71 Curb box

● Curb Box

Main

Elev. of Main at tap

Gate at ● ● Gate at

25' to main

3/4" Copper ● Curb Box