

LABOR AND MATERIALS

1	Copper Lead	{ Connection	$\frac{3}{4}$	\$ 1.31
1	Curb	{ Cock Valve T. S. & V.	$\frac{3}{4}$ in.	\$ 1.75
1	Service Box	}	Short $\frac{3}{2} \times \frac{4}{1}{2}$	\$ 1.60
	Old returned		Long $\frac{4}{1}{2} \times \frac{5}{1}{2}$	
			Buff. or Rdway	
25	Ft. $\frac{3}{4}$ in.	{ Copper Galv. Iron Cast Iron	Pipe at 18	\$ 4.50

	Nipples	in. at		\$
	Bushings	to in. at		\$
	Red'g Inc'g	Couplings to in. at		\$

	Union	in. at		\$

	Meter	in. at		\$

	Lead Joints at			\$

	Leadite Joints at			\$

	Hrs. Foreman at			\$

7	Hrs. Tapper at	62 1/2	44	\$ 44

	Hrs. Labor at			\$

9	Hrs. Labor at	45	405	\$ 405

	Hrs. Compressor at			\$

	Compensation Ins.			\$.14

	Trucking			\$ 1

	Builders Use of Water	Before Paving		\$

	<i>Top 1/4 Hassel</i>			\$

				\$

				\$

				\$

				\$

				\$

				\$

				\$

				\$ 14.79

6 0 - - 1940

St.

Fourth

~~Pl.~~

Ar. No. 79

Name of Owner

Ed Ball lot

Labor and Mat'l. Report

June 13 1940



● Curb Box

← 284' →

6 Main

Elev. of
Main at tap 44

Gate at ●

● Gate at

● Curb Box

Hydrant

