LABOR AND MATERIALS

1 Copper ~~Lead~~ Connection 3/4		$ 1.31
1 Curb Cock ~~Valve~~ ~~T. S. & V.~~ 3/4 in.		$ 1.75
1 Service Box ~~Old returned~~ Short 3½x4½ ~~Long 4½x5½~~ ~~Buff. or Rdway~~		$ 1.66
9 Ft. 3/4 in. Copper ~~Galv Iron~~ ~~Cast Iron~~ Pipe at 18		$ 1.62
Nipples in. at		$
Bushings to in. at		$
Red'g Inc'g Couplings to in. at		$
Union in. at		$
Meter in. at		$
Lead Joints at		$
Leadite Joints at		$
Hrs. Foreman at		$
Hrs. Chauffeur at		$
1/4 Hrs. Tapper at	62½	$ .16
Hrs. Labor at		$
3½ Hrs. Labor at	.45	$ 1.58
Hrs. Compressor at		$
Compensation Ins.		$ .06
Trucking		$ 1 —
Builders Use of Water	no patch	$
Tap by Hosed	EXT.	$ —
		$
		$
		$
		$ 9.08

8 8 - - 1940

St.
Fourth (hit) ~~Pl.~~ ~~Ave.~~ No. 82

Name of Owner
Thomas

Labor and Mat'l. Report July 15 1940

Tap in cen[illegible] of 50' lot

● Curb Box

6 Main

Elev. of Main at tap 5

Gate at ●

● Gate at

● Curb Box