

# LABOR AND MATERIALS

1	Copper Lead } Connection	$\frac{1}{2}$ "	\$	_____
1	Curb } Cock Valve T.G.-&V. }	$\frac{3}{4}$ " in.	\$	_____
1	Service box } <del>Old returned</del> }	{ Short 3-1/2 x 4-1/2 Long 4-1/2 x 6-1/2 }	\$	_____
23	Ft. $\frac{3}{4}$ in. { Copper G.I. } Pipe at		\$	_____
1	Nipples $\frac{1}{2}$ in. at		\$	_____
	Bushings _____ to _____ in. at		\$	_____
1	Red'g $\frac{1}{2}$ to $\frac{3}{4}$			
	Inc'g			
	Union _____ in. at		\$	_____
	Meter _____ in. at		\$	_____
			\$	_____
	Compound Joints at		\$	_____
	Maintenance Foreman		\$	_____
	Hrs. Water Maint. Man - 1 at		\$	_____
	Hrs. Water Maint. Man - 2 at		\$	_____
	Hrs. Garage Foreman _____ at		\$	_____
	Hrs. Labor _____ at		\$	_____
	Hrs. Compressor at		\$	_____
			\$	_____
	Trucking		\$	_____
	Pav't Patch		\$	_____
			\$	_____
			\$	_____
			\$	_____
			\$	_____

FOURTH

St. Ave. No. 10

Name of Owner  
TAX ID # 309.12-14-9

Labor and Mat'l. Report 19 23, DEC. 3



13'-9" 17'-9"

● Curb Box

6" Main

Elev. of Main at tap 4'

Gate at ●

● Gate at

23' to main

3/4" GAL.

● Curb Box