

### LABOR AND MATERIALS

1	Copper	Connection	<u>3/4"</u>		\$		
	Lead						
1	Curb	Cock Valve	<u>3/4</u> in.		\$		
		T. S. & V.					
	Service box	}	Short 3 1/2 x 4 1/2				
	Old returned		Long 4 1/2 x 5 1/2				
			Buff or Rdway		\$		
25	Ft.	}	Copper	Pipe at			
	<u>3/4</u> in.		C. I.			\$	
			C. I.				
	Nipples		in. at		\$		
	Bushings		to in. at		\$		
	Red'g	}	Coupl'gs	to in. at			
	Inc'g					\$	
	Union		in. at		\$		
	Meter		in. at		\$		
	Lead Joints		at		\$		
	Compound Joints		at		\$		
	Maintenance Foreman				\$		
	Hrs. Water Maint. Man—1		at		\$		
	Hrs. Water Maint. Man—2		at		\$		
	Hrs. Garage Foreman		at		\$		
	Hrs. Labor—		at		\$		
	Hrs. Compressor		at		\$		
	Compensation Ins. at \$		per C.		\$		
	Trucking				\$		
	Pav't Patch				\$		
					\$		
					\$		
	O'head				\$		
					\$		

St. Fourth ST  
 Pl. 85  
 Ave. No. 85

---

Name of Owner Coulter

---

Lot Tap made in July

Labor and Mat'l. Report July 1940

---

Garage

33'4"

44'6"

● Curb Box

Measured in Dec. 16-14

---

10" C.I. Main

Elev. of Main at tap 5'

---

Gate at ● ● Gate at

---

● Curb Box