LABOR AND MATERIALS

1	Copper ~~Lead~~ Connection	3/4	$ 1.31
1	Curb Cock ~~Valve~~ ~~T. S. & V.~~	3/4 in.	$ 1.75
1	Service Box Old returned Short 3½x4½ / Long 4½x5½ / Buff. or Rdway		$ 1.60
9 Ft.	3/4 in. Copper ~~Galv Iron~~ ~~Cast Iron~~ Pipe at	18	$ 1.62½
	Nipples in. at		$
	Bushings to in. at		$
	Red'g Inc'g Couplings to in. at		$
	Union in. at		$
	Meter in. at		$
	Lead Joints at		$
	Leadite Joints at		$
	Hrs. Foreman at		$
	Hrs. Chauffeur at		$
14	Hrs. Tapper at	62½	$ .16
	Hrs. Labor at		$
31½	Hrs. Labor at	45	$ 1.58
	Hrs. Compressor at		$
	Compensation Ins.		$ .06
	Trucking		$ 1.—
	Builders Use of Water No Patch-Exc.		$
	Tap by Hassel		$
			$
			$
			$
			$ 9.08

9 3 - 1940

St. ~~Pl.~~ ?

Fourth Lot Ave. No. 90

Name of Owner

Thomas

Labor and Mat'l. Report July 17 1940

Tap in center of 50' Lot

● Curb Box

6 Main

Elev. of Main at tap 5-

Gate at ●

● Gate at

● Curb Box