

LABOR AND MATERIALS

1	Copper	Connection	3/4	\$ 1.31
1	Lead			
1	Curb	Cock Valve I.S. & V.	3/4 in.	\$ 1.75
1	Service Box	Short 3 1/2 x 4 1/2		\$ 1.60
	Old returned	Long 4 1/2 x 5 1/2		
9	Ft.	3/4 in.	Pipe at	18 \$ 1.62
	Nipples	in. at		\$
	Bushings	to in. at		\$
	Red'g Inc'g	Couplings to in. at		\$
	Union	in. at		\$
	Meter	in. at		\$
	Lead Joints	at		\$
	Leadite Joints	at		\$
	Hrs. Foreman	at		\$
	Hrs. Chauffeur	at		\$
14	Hrs. Tapper	at	62 1/2	\$.16
	Hrs. Labor	at		\$
3 1/2	Hrs. Labor	at	45	\$ 1.58
	Hrs. Compressor	at		\$
	Compensation Ins.			\$.06
	Trucking			\$ 1
	Builders Use of Water	no patch E.T.		\$
	Tap by House			\$
				\$
				\$
				\$
				\$
				\$ 9.08

9 1 - - 1940

St.

? 92

Pt.

Fourth (West) Ave. No. 86

Name of Owner

Thomas

Labor and Mat'l. Report

July 16 1940

Tap in center of
50' lot

● Curb Box

6 Main

Elev. of Main at tap 5

Gate at ●

● Gate at

● Curb Box

Lot Divided in
Two parts,