

LABOR AND MATERIALS

Copper } Connection _____	\$ _____
Lead } _____	
Curb } Cock _____	in. \$ _____
} Valve _____	
} T. S. & V. _____	
Service box } Short 3½ x 4½ } _____	
Old returned } Long 4½ x 5½ } _____	\$ _____
Ft. ¾ in. } Copper } Pipe at _____	\$ _____
} G.I. } _____	
} C.I. } _____	
Nipples _____ in. at _____	\$ _____
Bushings _____ to _____ in. at _____	\$ _____
Red'g } Coupl'gs _____ to _____ in. at _____	\$ _____
Inc'g } _____	
Union _____ in. at _____	\$ _____
Meter _____ in. at _____	\$ _____
_____	\$ _____
Compound Joints at _____	\$ _____
Maintenance Foreman _____	\$ _____
Hrs. Water Maint. Man—1 at _____	\$ _____
Hrs. Water Maint. Man—2 at _____	\$ _____
Hrs. Garage Foreman _____ at _____	\$ _____
Hrs. Labor— _____ at _____	\$ _____
Hrs. Compressor at _____	\$ _____
_____	\$ _____
Trucking _____	\$ _____
Pav't Patch _____	\$ _____
_____	\$ _____
_____	\$ _____
_____	\$ _____
_____	\$ _____
_____	\$ _____

Franklin + Faxon

Franklin

St. Pt. Ave. No. 30

Name of Owner

JEFF GORHAM

Labor and Mat'l. Report

19 96



?

● Curb Box

Main

Elev. of

Main at tap

Gate at ●

● Gate at

TAP ON FAXON

● Curb Box

- This House is on the NE cor. of Franklin + FAXON - Face Faxon & within distance from Franklin