

# LABOR AND MATERIALS

1 Copper } Connection 3/4 \$ \_\_\_\_\_  
~~Lead~~  
 1 Curb } Cock 3/4 in. \$ \_\_\_\_\_  
~~Valve~~  
~~7.0-2.4.~~  
 1 Service box { Short 3-1/2 x 4-1/2 } \$ \_\_\_\_\_  
 Old returned { ~~Long 4-1/2 x 5-1/2~~ }  
 12 Ft. 3/4 in. { Copper } Pipe at \$ \_\_\_\_\_  
 Nipples \_\_\_\_\_ in. at \$ \_\_\_\_\_  
 Bushings \_\_\_\_\_ to \_\_\_\_\_ in. at \$ \_\_\_\_\_  
 Red'g \_\_\_\_\_  
 Inc'g \_\_\_\_\_  
 Union \_\_\_\_\_ in. at \$ \_\_\_\_\_  
 Meter \_\_\_\_\_ in. at \$ \_\_\_\_\_  
 \_\_\_\_\_ \$ \_\_\_\_\_  
 Compound Joints at \$ \_\_\_\_\_  
 Maintenance Foreman \$ \_\_\_\_\_  
 Hrs. Water Maint. Man - 1 at \$ \_\_\_\_\_  
 Hrs. Water Maint. Man - 2 at \$ \_\_\_\_\_  
 Hrs. Garage Foreman \_\_\_\_\_ at \$ \_\_\_\_\_  
 Hrs. Labor \_\_\_\_\_ at \$ \_\_\_\_\_  
 Hrs. Compressor at \$ \_\_\_\_\_  
 \_\_\_\_\_ \$ \_\_\_\_\_  
 Trucking \$ \_\_\_\_\_  
 Pav't Patch \$ \_\_\_\_\_  
 \_\_\_\_\_ \$ \_\_\_\_\_  
 \_\_\_\_\_ \$ \_\_\_\_\_  
 \_\_\_\_\_ \$ \_\_\_\_\_  
 \_\_\_\_\_ \$ \_\_\_\_\_  
 \_\_\_\_\_ \$ \_\_\_\_\_

St. FULTON  
 Ave. No. 32

Name of Owner  
CLARENCE HOYT

Labor and Mat'l. Report 1937, JUNE 18



18-5 17-1

● Curb Box

10" Main Elev. of Main at tap 4 1/2'

Gate at ● Gate at

TAX ID # 302.16-21-24

● Curb Box

OLD SHUT OFF