

# LABOR AND MATERIALS

1 Copper } Connection <sup>3/4</sup> \$ \_\_\_\_\_  
~~1~~ }  
 1 Curb } Cock } <sup>3/4</sup> in. \$ \_\_\_\_\_  
 } Valve }  
 } T.S. & V. }  
 1 Service box { Short 3-1/2 x 4-1/2 } \$ \_\_\_\_\_  
 Old returned { Long 4-1/2 x 5-1/2 }  
 25 Ft. <sup>3/4</sup> in. { Copper } Pipe at \$ \_\_\_\_\_  
 }  
 }  
 Nipples \_\_\_\_\_ in. at \$ \_\_\_\_\_  
 Bushings \_\_\_\_\_ to \_\_\_\_\_ in. at \$ \_\_\_\_\_  
 Red'g \_\_\_\_\_  
 Inc'g \_\_\_\_\_  
 Union \_\_\_\_\_ in. at \$ \_\_\_\_\_  
 Meter \_\_\_\_\_ in. at \$ \_\_\_\_\_  
 \_\_\_\_\_ \$ \_\_\_\_\_  
 Compound Joints at \$ \_\_\_\_\_  
 Maintenance Foreman \$ \_\_\_\_\_  
 Hrs. Water Maint. Man - 1 at \$ \_\_\_\_\_  
 Hrs. Water Maint. Man - 2 at \$ \_\_\_\_\_  
 Hrs. Garage Foreman \_\_\_\_\_ at \$ \_\_\_\_\_  
 Hrs. Labor \_\_\_\_\_ at \$ \_\_\_\_\_  
 Hrs. Compressor at \$ \_\_\_\_\_  
 \_\_\_\_\_ \$ \_\_\_\_\_  
 Trucking \$ \_\_\_\_\_  
 Pav't Patch \$ \_\_\_\_\_  
 \_\_\_\_\_ \$ \_\_\_\_\_  
 \_\_\_\_\_ \$ \_\_\_\_\_  
 \_\_\_\_\_ \$ \_\_\_\_\_  
 \_\_\_\_\_ \$ \_\_\_\_\_

St. \_\_\_\_\_  
GARFIELD Ave. No. 34

Name of Owner \_\_\_\_\_

Labor and Mat'l. Report 19 28, AUG. 21



26'4" 26'4"

● Curb Box

6" Main Elev. of Main at tap 4 1/4'

Gate at ● Gate at ●

● Curb Box

OLD TAP SHUT OFF