

## LABOR AND MATERIALS

1	Copper <del>Lead</del>	} Connection	3/4		\$
1	Curb	{ Cock Valve T. S. & V.	3/4	in.	\$
	Service Box Old returned	{ Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2 Buffer Rdway			\$
23	Ft.	3/4 in.	{ Copper Galv Iron Cast Iron	} Pipe at	\$
	Nipples	..... in. at			\$
	Bushings	..... to ..... in. at			\$
	Red'g Inc'g	} Couplings..... to ..... in. at			\$
	Union	..... in. at			\$
	Meter	..... in. at			\$
	Lead Joints at				\$
	Leadite Joints at				\$
	Hrs. Foreman at				\$
	Hrs. Chauffeur at				\$
	Hrs. Tapper at				\$
	Hrs. Labor at				\$
	Hrs. Labor at				\$
	Hrs. Compressor at				\$
	Compensation Ins.				\$
	Trucking				\$
	Builders Use of Water				\$
					\$
					\$
					\$
					\$
					\$

St. 40  
~~St.~~  
 Ave. No. 35

*Garfield*

Name of Owner  
TAP INSTALLED 6-28-30

---

Labor and Mat'l. Report AUG 24 1939 19

---

6" Main
Elev. of Main at tap 5'

Gate at ●
● Gate at

---

● Curb Box