

LABOR AND MATERIALS

1	Copper } Connection		\$
	Lead } Cock		
1	Curb } Valve	in.	\$
1	Service box { Short 3-1/2 x 4-1/2		\$
	Old returned { Long 4-1/2 x 5-1/2		
23	Ft. 3/4 in. { Copper		\$
		Pipe at	
	Nipples	in. at	\$
1	Bushings 3/4 to 1/2	in. at	\$
	Red'g		
	Inc'g		
	Union	in. at	\$
	Meter	in. at	\$
			\$
	Compound Joints at		\$
	Maintenance Foreman		\$
	Hrs. Water Maint. Man - 1 at		\$
	Hrs. Water Maint. Man - 2 at		\$
	Hrs. Garage Foreman	at	\$
	Hrs. Labor	at	\$
	Hrs. Compressor at		\$
			\$
	Trucking		\$
	Pav't Patch		\$
			\$
			\$
			\$
			\$

St. GARFIELD
 Ave. No. 14
 Name of Owner _____

Labor and Mat'l. Report 1931, APR. 24



34 4/3-3

● Curb Box

6" Main Elev. of Main at tap 5'
 Gate at ● Gate at ●

TAX ID # 302.19-18-2

● Curb Box

OLD TAP DISCONNECTED