

# LABOR AND MATERIALS

1	Copper } Connection	<u>3/4</u>	\$
1	Curb } Cock Valve	<u>3/4</u> in.	\$
1	Service box } Short 3-1/2 x 4-1/2		\$
	Old returned } Long 4-1/2 x 5-1/2		\$
11	Ft. <u>3/4</u> in. } Copper	Pipe at	\$
	Nipples	in. at	\$
	Bushings	to in. at	\$
	Red'g		\$
	Inc'g		\$
	Union	in. at	\$
	Meter	in. at	\$
	Compound Joints at		\$
	Maintenance Foreman		\$
	Hrs. Water Maint. Man - 1 at		\$
	Hrs. Water Maint. Man - 2 at		\$
	Hrs. Garage Foreman	at	\$
	Hrs. Labor	at	\$
	Hrs. Compressor at		\$
	Trucking		\$
	Pav't Patch		\$
			\$
			\$
			\$
			\$
			\$
			\$

GEER

St. 46  
Ave. No.

Name of Owner

Labor and Mat'l. Report 19 34, MAY 17



26-10 20-6

● Curb Box

4" Main

Elev. of Main at tap 4'

Gate at ●

● Gate at

● Curb Box

OLD TAP SHUT OFF AT MAIN