

LABOR AND MATERIALS

1	Copper } Connection	3/4	\$	_____
1	Lead } Cock	3/4 in.	\$	_____
1	Curb } Valve		\$	_____
	I.S. & V.		\$	_____
1	Service box { Short 3-1/2 x 4-1/2		\$	_____
	Old returned { Long 4-1/2 x 5-1/2		\$	_____
26	Ft. 3/4 in. { Copper		\$	_____
	Old		\$	_____
	Old		\$	_____
	Nipples	_____ in. at _____	\$	_____
	Bushings	_____ to _____ in. at _____	\$	_____
	Red'g		\$	_____
	Inc'g		\$	_____
	Union	_____ in. at _____	\$	_____
	Meter	_____ in. at _____	\$	_____
	Compound Joints at _____		\$	_____
	Maintenance Foreman _____		\$	_____
	Hrs. Water Maint. Man - 1 at _____		\$	_____
	Hrs. Water Maint. Man - 2 at _____		\$	_____
	Hrs. Garage Foreman _____ at _____		\$	_____
	Hrs. Labor _____ at _____		\$	_____
	Hrs. Compressor at _____		\$	_____
	Trucking _____		\$	_____
	Pav't Patch _____		\$	_____
			\$	_____
			\$	_____
			\$	_____
			\$	_____

GEER

St.

No.

49

Name of Owner

Labor and Mat'l. Report 1925, AUG 18



20'-0 26'-0

● Curb Box

4" Main

Elev. of Main at tap

3 1/2'

Gate at ●

● Gate at

● Curb Box

DUG UP + CKED FOR COPPER,
FOUND COPPER PIPE 8-30-62