

LABOR AND MATERIALS

1	Copper	Connection	$\frac{3}{4}$	\$
1	Curb	Cock Valve	$\frac{3}{4}$ in.	\$
1	Service box	Short 3-1/2 x 4-1/2		\$
	Old returned	Long 4-1/2 x 5-1/2		\$
8	Ft.	$\frac{3}{4}$ in. Copper	Pipe at	\$
	Nipples		in. at	\$
1	Bushings	$\frac{1}{2}$ to $\frac{3}{4}$	in. at	\$
	Red'g			\$
	Inc'g			\$
	Union		in. at	\$
	Meter		in. at	\$
	Compound Joints at			\$
	Maintenance Foreman			\$
	Hrs. Water Maint. Man - 1 at			\$
	Hrs. Water Maint. Man - 2 at			\$
	Hrs. Garage Foreman		at	\$
	Hrs. Labor		at	\$
	Hrs. Compressor at			\$
	Trucking			\$
	Pav't Patch			\$
				\$
				\$
				\$
				\$

St. GLEN Ass. No. 405-409

Name of Owner _____

Labor and Mat'l. Report 1931, NOV. 2



G
N
E
L
S
T.

22-8 34-10
 or
 35-4
● Curb Box

NOTRE DAME ST

6" Main Elev. of Main at tap 5'

Gate at ● ● Gate at

● Curb Box

TAP ON NOTRE DAME
OLD TAP TO BE SHUT OFF