

LABOR AND MATERIALS

1	Copper	}	Connection	1"		\$
	Lead					
1	Curb	}	Cock Valve	1 in.		\$
			T.S. & V.			
1	Service box	}	Short 3 1/2 x 4 1/2			
	Old returned		Long 4 1/2 x 5 1/2			
			Buff or Rdway			\$
31	Ft. 1 in.	}	Copper	Pipe at		\$
			G.I.			
			C.I.			
	Nipples		in. at			\$
	Bushings		to in. at			\$
	Red'g	}	Coupl'gs	to in. at		\$
	Inc'g					
	Union		in. at			\$
	Meter		in. at			\$
	Lead Joints		at			\$
	Compound Joints		at			\$
	Maintenance Foreman					\$
	Hrs. Water Maint. Man—1		at			\$
	Hrs. Water Maint. Man—2		at			\$
	Hrs. Garage Foreman		at			\$
	Hrs. Labor—		at			\$
	Hrs. Compressor		at			\$
	Compensation Ins. at \$		per C			\$
	Trucking					\$
	Pav't Patch					\$
	Tap by Gifford & Co.					\$
	4-27-61.					\$
	O'head					\$

St. _____
 Pl. _____
 Ave. No. 420

Glen

Name of Owner
Metropolitan Life Ins. Co.

Labor and Mat'l. Report Apr 27 1961

45"

34' 8"

● Curb Box

1 1/2" Main Elev. of Main at tap 5 1/2"

Gate at ● ● Gate at

● Curb Box