

LABOR AND MATERIALS

Copper } Connection \$
 Lead }
 Curb { Cock Valve } in. \$
 { T. S. & V. }
 Service Box { Short 3½x4¼ } \$
 Old returned { Long 4½x5¼ }
 { Buff or Rdway }
 Ft. in. { Copper } Pipe at \$
 { Galv Iron }
 { Cast Iron }
 Nipples in. at \$
 Bushings to in. at \$
 Red'g } Couplings to in. at \$
 Inc'g }
 Union in. at \$
 Meter in. at \$
 Lead Joints at \$
 Leadite Joints at \$
 Hrs. Foreman at \$
 Hrs. Chauffeur at \$
 Hrs. Tapper at \$
 Hrs. Labor at \$
 Hrs. Labor at \$
 Hrs. Compressor at \$
 Compensation Ins. \$
 Trucking \$
 Builders Use of Water \$
 \$
 \$
 \$
 \$
 \$

St. 480
Pl.
Ave. No. 2016

Glen

Name of Owner
TAX ID # 302.16-9-6

Labor and Mat'l. Report **AUG 23 1939** 19

● Curb Box

Main Elev. of Main at tap.....

Gate at ● ● Gate at

Files on Application Card are different - Try those if these don't work

28' 9" 37' 3"