

LABOR AND MATERIALS

1	Copper	Connection	\$
1	Lead		\$
1	Curb	Cock Valve } in. \$	
		T.S. & V. }	
1	Service box	Short 3 1/2 x 4 1/2 } Long 4 1/2 x 5 1/2 } Buff or Rdway }	\$
1	Old returned		\$
9	Ft. 3/4 in.	Copper } G.I. } C.I. }	Pipe at \$
	Nipples	in. at	\$
	Bushings	to in. at	\$
	Red'g		\$
	Inc'g	Coupl'gs. to in. at	\$
	Union	in. at	\$
	Meter	in. at	\$
	Lead Joints	at	\$
	Compound Joints	at	\$
	Maintenance Foreman		\$
	Hrs. Water Maint. Man-1	at	\$
	Hrs. Water Maint. Man-2	at	\$
	Hrs. Garage Foreman	at	\$
	Hrs. Labor	at	\$
	Hrs. Compressor	at	\$
	Compensation Ins. at \$	per C	\$
	Trucking		\$
	Pav't Patch		\$
	Tap by Gifford & Co.		\$
	7-14-59.		\$
	O'head		\$

St. Glen  
-Pl. 575  
Ave. No. 575

Name of Owner J. P. Huning

Labor and Mat'l. Report July 14 1959

Glen St.

Curb Box

Monument Ave.

6" Main      Elev. of Main at tap 4 1/2'

Gate at ●      ● Gate at

● Curb Box

Tap on Monument Ave.

LSM-SC-2-5 56