

Labor and Materials

1 Copper } Connection	6" 1/2 Taping sleeve		
Lead			
1 Curb } Cock			
Value	in. x Valve	\$ 56.19	
T. S. & V.			
1 Service Box } Short 3 1/2 x 4 1/2	Gate box	\$ 7.50	
Old returned			Long 4 1/2 x 5 1/2
			Buff. or Rdway
58 Ft. 6" in. } Copper	Pipe at	77 \$ 40.81	
			Galv. Iron
	Cast Iron		
Nipples	in. at	\$	
Bushings	to in. at	\$	
Red'g } Couplings	to in. at	\$	
Inc'g			
Union	in. at	\$	
Meter	in. at	\$	
Lbs. Br. Stone at		\$	
Lbs. Sand at		\$	
Bags Cement at		\$	
Paving Brick } Mack	at	\$	
			Red
			Asphalt
Lead Joints at	1.50 ft. 9.1 lb joints	\$ 15.50	
4 Leadite Joints at	Gal. G. S.	\$ .68	
34 Hrs. Foreman at	62 1/2	\$ 21.25	
20 Hrs. Common Labor at	50	\$ 10.00	
15 1/4 Hrs. Common Labor at	40 1/8	\$ 62.56	
Hrs. Mason at		\$	
Hrs. Mason's Helper at		\$	
7 Hrs. Compressor at		\$ 10.50	
Compensation Ins		\$ 2.49	
Trucking		\$ 5.00	
Builders' Use of Water	at	\$ 50.-	
Total \$		282.25	
		268.14	

29-113

Labor and Material Report

Apr 27

1929

6" tap at 118 Glen st



12"

Main

Elev of Main at tap

42

Gate at ●

● Gate at

Tap Bar

● Curb Box

6" Sprinkler system

50  
56.50  
113.50  
56.50