

LABOR AND MATERIALS

1	Copper	Connection	1"	\$	2.79
1	Lead				
1	Curb	Clock Valve	1" in.	\$	3.60
		F.S. & V.			
1	Service box	} Short 3 1/2 X 4 1/2 } Long 4 1/2 X 5 1/2 } Buff or Rdway		\$	1.82
	Old returned				
13 Ft.	1" in.	Copper Galv. Iron Cast Iron	Pipe at	\$	32.99
	Nipples	in. at		\$	
	Bushings	to in. at		\$	
	Red'g Inc'g	Couplings	to in. at	\$	
	Union	in. at		\$	
	Meter	in. at		\$	
	Lead Joints	at		\$	
	Compound Joints	at		\$	
	Hrs. Foreman	at		\$	
8	Hrs. Chauffeur	at	68 3/4	\$	5.50
12	Hrs. Tapper	at	62 1/2	\$	7.50
12	Hrs. Labor	at	60	\$	7.20
	Hrs. Labor	at		\$	
	Hrs. Compressor	at		\$	
	Compensation Ins.			\$.54
	Trucking			\$	1.00
	Builders Use of Water			\$	9.-
	Taphy Machine			\$	
	This tap from Park St			\$	
				\$	41.94

25 15

St. 124-26
Pl. - 98
Ave. No. _____

Name of Owner
Aranson

Labor and Mat'l. Report *Aug 31* 19 *45*

11'5" 22'5" Glen ST

● Curb Box
Park ST

8 Main Elev. of Main at tap 4

● Gate at ● Gate at

● Curb Box

LSM-5C-6-1-45 *Take Billed*

Labor and Materials

1	Copper Lead- Connection	6" tapping sleeve		\$
1	Curb Cock Valve T. S. & V.		in	\$
1	GATE Service Box Old-fashioned	Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2 Buff. or Rdway		\$
17	Ft. 6 in.	Copper Galv Iron Cast-iron	Pipe at	\$
	Nipples		in. at	\$
	Bushings		to in. at	\$
	Red'g Inc'g	Conplings	to in. at	\$
	Union		in. at	\$
	Meter		in. at	\$
	Lead Joints		at	\$
	Leadite Joints		at	\$
	Hrs. Foreman		at	\$
	Hrs. Chauffeur		at	\$
	Hrs. Tapper		at	\$
	Hrs. Labor		at	\$
	Hrs. Labor		at	\$
	Hrs. Compressor		at	\$
	Compensation Ins.			\$
	Trucking			\$
	Builders Use of Water			\$
				\$
				\$
				\$
				\$

124-126
Glen

St. Park Ave. No. 28

Name of Owner

Labor and Mat'l. Report 10/19/21 19

124-126
GLEN ST.
Curb Box

35-6
50-11

6" Main Park St Elev. of Main at tap 44'

Gate at • Gate at

• Curb Box

6" tap