


Labor and Materials

1. Lead Connection *6x9/100* ✓ \$  
 Curb Cock *1/2" x 1/2" x 1/2"* ✓ \$  
 Service Box (Short 3 1/2 x 4 1/2) *4" x 4" x 4"* ✓ \$  
 Old returned (Long 4 1/2 x 5 1/2) *Gate Box* \$  
 24 Ft. 4" in. G. I. Pipe at \$  
 Nipples . . . in. at \$  
 Bushings . . . to . . . in. at \$  
 Red'g Coup . . . to . . . in. at \$  
 Inc'g Coup . . . to . . . in. at \$  
 Union . . . in. at \$  
 Meter . . . in. at \$  
 Cu. Yds. Br. Stone at \$  
 Cu. Yds. Sand at \$  
 Bags Cement at \$  
 Paving Brick { Mack Red Asphalt } at \$  
 20 Hrs. Foreman at \$  
 48 Hrs. Common Labor at \$  
 Hrs. Mason at \$  
 Hrs. . . . at \$  
 19 Hrs. *Painter* . . . at \$  
 25 Builders' Use of Water . . . at \$  
 8 joints *Lead* . . . at \$  
 2 gal. Gas *July* . . . at \$  
*Track* . . . at \$  
 Total \$

148 158  
 Labor and Material Report July 23 19

4" Tap at 106 + 113  
 This is the *Elm St*  
 measurement for 106 + 113  

 148-158

Elm St.

6' Main Elev. of Main at tap 4.12  
 Gate at ● Gate at ●

Meter Has been Removed.  
 Meter Korold  
 Rockwell House on  
 this Line in Rear of  
 Grant's store. This Tap  
 shut off at Curb.