

## LABOR AND MATERIALS

1	Copper Lead	{ Connection	2" _____		\$ 24.23
1	Curb	{ Cock Valve T. S. & V.	2 in. _____		\$ 20.53
1	Service box Old returned	{ Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2 Buff or Rdway	_____		\$ 11.15
12 Ft.	2 in.	{ Copper G.I. C.I.	Pipe at 92		\$ 11.04
	Nipples	in. at _____			\$ _____
	Bushings	to _____ in. at _____			\$ _____
1	Red'g Inc'g	{ Copper Coupl'gs	to 2 in. at _____		\$ _____
	Union	in. at _____			\$ _____
	Meter	in. at _____			\$ _____
	Lead Joints at _____				\$ _____
	Compound Joints at _____				\$ _____
14	Hrs. Water Maint. Man-1	at 123			\$ 17.22
1	Hrs. Water Maint. Man-2	at 113			\$ 11.3
42	Hrs. Labor	at 102			\$ 42.84
	Hrs. Labor	at _____			\$ _____
	Hrs. Compressor at _____				\$ _____
	Compensation Ins. at \$2.66 per C.				\$ 1.63
	Trucking				\$ 1.00
	Pay't Patch				\$ 10.08
	1-8" Dresser repair				\$ _____
	Shoe Style 82				\$ _____
	(3-B Sect.)				\$ _____
	O'head				\$ _____

St. \_\_\_\_\_  
Ht. \_\_\_\_\_  
Ave. No. 1-50

Name of Owner  
Glen Grant Store

Labor and Mat'l. Report Aug 20 1951



Small Roadway Gate • Curb Box  
Transite  
8" Main  
Elev. of Main at tap 5'

Gate at • Gate at  
Shut off at Curb JAN-27-1945

This • Curb Box  
Top is at 11-13  
Exchange St.