

# LABOR AND MATERIALS

- 1 Copper } Connection 1" \$ \_\_\_\_\_
- 1 Curb } Cock } 1" in. \$ \_\_\_\_\_
- 1 Service box } Short 3-1/2 x 4-1/2 } \$ \_\_\_\_\_
- Old returned } Long 4-1/2 x 5-1/2 } \$ \_\_\_\_\_
- 47 Ft. 1" in. } Copper } Pipe at \$ \_\_\_\_\_
- Nipples \_\_\_\_\_ in. at \$ \_\_\_\_\_
- Bushings \_\_\_\_\_ to \_\_\_\_\_ in. at \$ \_\_\_\_\_
- Red'g \_\_\_\_\_
- Inc'g \_\_\_\_\_
- Union \_\_\_\_\_ in. at \$ \_\_\_\_\_
- Meter \_\_\_\_\_ in. at \$ \_\_\_\_\_
- \_\_\_\_\_ \$ \_\_\_\_\_
- Compound Joints at \$ \_\_\_\_\_
- Maintenance Foreman \$ \_\_\_\_\_
- Hrs. Water Maint. Man - 1 at \$ \_\_\_\_\_
- Hrs. Water Maint. Man - 2 at \$ \_\_\_\_\_
- Hrs. Garage Foreman \_\_\_\_\_ at \$ \_\_\_\_\_
- Hrs. Labor \_\_\_\_\_ at \$ \_\_\_\_\_
- Hrs. Compressor at \$ \_\_\_\_\_
- \_\_\_\_\_ \$ \_\_\_\_\_
- Trucking \_\_\_\_\_ \$ \_\_\_\_\_
- Pav't Patch \_\_\_\_\_ \$ \_\_\_\_\_
- \_\_\_\_\_ \$ \_\_\_\_\_
- \_\_\_\_\_ \$ \_\_\_\_\_
- \_\_\_\_\_ \$ \_\_\_\_\_
- \_\_\_\_\_ \$ \_\_\_\_\_
- \_\_\_\_\_ \$ \_\_\_\_\_

St. GLEN Ave. No. 160-64  
 Name of Owner \_\_\_\_\_

Labor and Mat'l. Report 1929, MAY 22



35'-7" 16'-2"

● Curb Box

12" Main Elev. of Main at tap 5 1/2'

Gate at ● Gate at ●

● Curb Box