

LABOR AND MATERIALS

1 Copper } Connection 1" \$ _____
 1 Curb } Cock } 1" in. \$ _____
 } Valve }
 } T.C. & V. }
 1 Service box { Short 3-1/2 x 4-1/2 } \$ _____
 Old returned { Long 4-1/2 x 5-1/2 }
 47 Ft. 1" in. { Copper } Pipe at \$ _____
 _____ Nipples _____ in. at \$ _____
 _____ Bushings _____ to _____ in. at \$ _____
 _____ Red'g _____
 _____ Inc'g _____
 _____ Union _____ in. at \$ _____
 _____ Meter _____ in. at \$ _____
 _____ Compound Joints at \$ _____
 _____ Maintenance Foreman \$ _____
 _____ Hrs. Water Maint. Man - 1 at \$ _____
 _____ Hrs. Water Maint. Man - 2 at \$ _____
 _____ Hrs. Garage Foreman _____ at \$ _____
 _____ Hrs. Labor _____ at \$ _____
 _____ Hrs. Compressor at \$ _____
 _____ Trucking \$ _____
 _____ Pav't Patch \$ _____
 _____ \$ _____
 _____ \$ _____
 _____ \$ _____
 _____ \$ _____
 _____ \$ _____

GLEN

St. _____
 Assn. No. 170-172

Name of Owner _____

Labor and Mat'l. Report 19 29, MAY 22



20'-11" 2'-2"

● Curb Box

12" Main

Elev. of Main at tap 5 1/2'

Gate at ●

● Gate at

● Curb Box