

LABOR AND MATERIALS

1	Copper Lead	Connection	1 1/2"	\$
1	Curb	Cock Valve T.S. & V.	1 1/2 in.	\$
1	Service box Old returned	Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2 Buff or Rdway		\$
43	Ft. 1 1/2 in.	Copper G.I. G.I.	Pipe at	\$
1	Nipples 1 1/2 in.	at	Male Adapters	\$
	Bushings	to	in. at	\$
	Red'g			\$
	Inc'g	Coupl'gs	to in. at	\$
2	Unions 1 1/2 in.	at	3 Piece	\$
	Meter	in. at		\$
	Lead Joints	at		\$
	Compound Joints	at		\$
	Maintenance Foreman			\$
	Hrs. Water Maint. Man-1	at		\$
	Hrs. Water Maint. Man-2	at		\$
	Hrs. Garage Foreman	at		\$
	Hrs. Labor	at		\$
	Hrs. Compressor at			\$
	Compensation Ins. at \$	per C		\$
	Trucking			\$
	Pay't Patch			\$
	Tap by Miller & Co.			\$
	9-21-56			\$
	O'head			\$
				\$

St. 174
Pl. 174
Ave. No. 176

Glen

Name of Owner
Russell & Waite

Labor and Mat'l. Report Sept. 21 19 56

12" Main

Elev. of Main at tap 5 1/2'

Gate at • • Gate at

• Curb Box

LSM-5C-2-5 56