



**Labor and Materials**

Copper } Connection.....	\$	
Lead } .....	\$	
1 Curb } <del>Cock</del> Valve } 12x in. 6" Express	\$52.00	
T. S. & V. } .....		
Service Box } Short 3 x 4 1/2	\$7.70	}
Old returned } Long 4 x 5 1/2		
Buff. or Rdway } .....		
17 Ft. 6 in. } Copper } Pipe at	\$47.00	
} Galv. Iron } .....		
} Cast Iron } .....		
Nipples..... in. at.....	\$	
Bushings..... to..... in. at.....	\$	
Red'g } Couplings..... to..... in. at.....	\$	
Inc'g } .....		
Union..... in. at.....	\$	
Meter..... in. at.....	\$	
Lbs. Br. Stone at.....	\$	
Lbs. Sand at... Pawt Patch	\$97.48	
Bags Cement at.....	\$	
Paving Brick } Mack } at.....	\$	
} Red } .....		
} Asphalt } .....		
1 Lead Joints at 12"	\$3.25	
6 Lead Joints at 1 1/2"	\$7.50	
5.6 Hrs. Foreman at... 52 1/2"	\$35.-	
71 Hrs. Common Labor at... 50"	\$35.50	
86 Hrs. Common Labor at... 40 1/2"	\$24.94	
Hrs. Mason at.....	\$	
Hrs. Mason's Helper at.....	\$	
6 Hrs. Compressor at.....	\$12.-	
Compensation Ins.....	\$2.95	
12 Trucking.....	\$12.-	
Builders' Use of Water.....	\$	
Total		\$347.82

26-183 190-194

Labor and Material Report

1929

190-194

8' 10"

59' 10"

Curb Box

12" Main

Elev. of Main at top 4 1/2

Gate at

Gate at

Curb Box

Shut off Feb 19-21  
using tap at 133-135 Glen

Billed  
11-30-26