

LABOR AND MATERIALS

1	Copper	} Connection	1"	\$
1	Curb		} 1" in.	\$
1	Service box	{		Short 3-1/2 x 4-1/2
	Old returned		Long 4-1/2 x 5-1/2	\$
9	Ft. 1"	} Copper	Pipe at	\$
	Nipples	in. at		\$
	Bushings	to in. at		\$
	Red'g			
	Inc'g			
	Union	in. at		\$
	Meter	in. at		\$
				\$
	Compound Joints at			\$
	Maintenance Foreman			\$
	Hrs. Water Maint. Man - 1 at			\$
	Hrs. Water Maint. Man - 2 at			\$
	Hrs. Garage Foreman	at		\$
	Hrs. Labor	at		\$
	Hrs. Compressor at			\$
				\$
	Trucking			\$
	Pav't Patch			\$
				\$
				\$
				\$
				\$

GLEN

St.

No.

195-199

Name of Owner

Labor and Mat'l. Report 19 28, AUG 16



27'7" 21'6"

● Curb Box

12" Main

Elev. of Main at tap 4'

Gate at ●

● Gate at

9' to main

● Curb Box

OLD TAP SHUT OFF