

LABOR AND MATERIALS

1	Copper	Connection	1"	\$
1	Curb	Cock Valve	1" in.	\$
1	Service box	Short 3-1/2 x 4-1/2	5x6'	\$
	Old returned	Long 4-1/2 x 5-1/2		
47	Ft.	1" in.	Copper Pipe	\$
	Nipples		in. at	\$
	Bushings		to in. at	\$
	Red'g			
	Inc'g			
	Union		in. at	\$
	Meter		in. at	\$
				\$
	Compound Joints		at	\$
	Maintenance Foreman			\$
	Hrs. Water Maint. Man - 1		at	\$
	Hrs. Water Maint. Man - 2		at	\$
	Hrs. Garage Foreman		at	\$
	Hrs. Labor		at	\$
	Hrs. Compressor		at	\$
				\$
	Trucking			\$
	Pav't Patch			\$
				\$
				\$
				\$
				\$

GLEN St. No. 196-198

Name of Owner
TAX ID # 302.20-28-4

Labor and Mat'l. Report 1929, MAY 22

ENGLANDER

27'8" 19'2"

● Curb Box

12" Main

Elev. of Main at tap 5 1/2'

Gate at ●

● Gate at

● Curb Box

1" TAP

NO. 95