

LABOR AND MATERIALS

Copper } Connection _____ \$ _____	
Lead } _____ \$ _____	
1 Curb } ^{Check} Valve } _____ in. 12x6 \$ _____	
	T.S. & V. }
1 Service box { Short 3-1/2 x 4-1/2 } _____ \$ _____	
Old returned { Long 4-1/2 x 5-1/2 }	
49 Ft. 6 in. { ^{Copper} } Pipe at _____ \$ _____	
	{ C.I. }
_____ Nipples _____ in. at _____ \$ _____	
_____ Bushings _____ to _____ in. at _____ \$ _____	
_____ Red'g _____	
_____ Inc'g _____	
_____ Union _____ in. at _____ \$ _____	
_____ Meter _____ in. at _____ \$ _____	
_____ \$ _____	
_____ Compound Joints at _____ \$ _____	
_____ Maintenance Foreman _____ \$ _____	
_____ Hrs. Water Maint. Man - 1 at _____ \$ _____	
_____ Hrs. Water Maint. Man - 2 at _____ \$ _____	
_____ Hrs. Garage Foreman _____ at _____ \$ _____	
_____ Hrs. Labor _____ at _____ \$ _____	
_____ Hrs. Compressor at _____ \$ _____	
_____ \$ _____	
_____ Trucking _____ \$ _____	
_____ Pav't Patch _____ \$ _____	
_____ \$ _____	
_____ \$ _____	
_____ \$ _____	
_____ \$ _____	
_____ \$ _____	

GLEN St. No. 220
 Name of Owner

Labor and Mat'l. Report 19 29, MAY 22

WOOLWORTH

28' 2" HYD
 20' 4"
 ● Curb Box

12" Main Elev. of Main at tap 52'
 Gate at ● Gate at ●

TAX ID # 302.20-28-8

● Curb Box

6" SPRINKLER SYSTEM

LABOR AND MATERIALS

_____ Copper } Connection _____ \$ _____
 _____ Lead }
 _____ Curb } Cock _____ in. _____ \$ _____
 _____ Valve }
 _____ T.S. & V. }
 _____ Service box { Short 3-1/2 x 4-1/2 } _____ \$ _____
 _____ Old returned { Long 4-1/2 x 5-1/2 }
 _____ Ft. 1" in. { Copper } Pipe at _____ \$ _____
 _____ Nipples _____ in. at _____ \$ _____
 _____ Bushings _____ to _____ in. at _____ \$ _____
 _____ Red'g _____
 _____ Inc'g _____
 _____ Union _____ in. at _____ \$ _____
 _____ Meter _____ in. at _____ \$ _____
 _____ \$ _____
 _____ Compound Joints at _____ \$ _____
 _____ Maintenance Foreman _____ \$ _____
 _____ Hrs. Water Maint. Man - 1 at _____ \$ _____
 _____ Hrs. Water Maint. Man - 2 at _____ \$ _____
 _____ Hrs. Garage Foreman _____ at _____ \$ _____
 _____ Hrs. Labor _____ at _____ \$ _____
 _____ Hrs. Compressor at _____ \$ _____
 _____ \$ _____
 _____ Trucking _____ \$ _____
 _____ Pav't Patch _____ \$ _____
 _____ \$ _____
 _____ \$ _____
 _____ \$ _____
 _____ \$ _____
 _____ \$ _____

GLEN

St. No. 220

Name of Owner

Labor and Mat'l. Report 19 56 OCT. 3

NO MEASUREMENTS - THIS SERVICE IS CONNECTED ON 6" FIRE LINE FOR BLD. NEAR CURB - SAME SIDE AS BLD.

● Curb Box

6" SPRENKLER
Main

Elev. of Main at tap

Gate at ●

● Gate at

● Curb Box