

Labor and Materials

1	Copper Lead	} Connection	3/4	in	\$	
1	Curb					
1	Service Box ON returned	} Cook Valve T. S. & V.	} 1"	in	\$	
47	Ft. 1					} Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2 Diff. or Rdway
	in.					
	Nipples	in. at	\$			
	Bushings	to	in. at	\$		
	Red'g Inc'g	} Conplings	to	in. at	\$	
	Union					in. at
	Meter	in. at	\$			
	Lead Joints	at	\$			
	Leadite Joints	at	\$			
	Hrs. Foreman	at	\$			
	Hrs. Chauffeur	at	\$			
	Hrs. Tapper	at	\$			
	Hrs. Labor	at	\$			
	Hrs. Labor	at	\$			
	Hrs. Compressor	at	\$			
	Compensation Ins.		\$			
	Trucking		\$			
	Builders Use of Water		\$			
			\$			
			\$			
			\$			
			\$			
			\$			
			\$			
			\$			

St. *Ellen* **282-286**
 Pt. **282-286**
 Ave. No. **186-8**

Name of Owner
Daniel A. Robertson

Labor and Mat'l. Report **11/16/22** 19

282-286

● Curb Box

Main Elev. of Main at tap.....

Gate at ● ● Gate at

● Curb Box