

LABOR AND MATERIALS

1	Copper	} Connection	1"	\$	
1	Lead				
1	Curb	} T.S. & V.	1" in.	\$	
1	Service box	} Short 3 1/2 x 4 1/2			
	Old returned		Long 4 1/2 x 5 1/2		
			Buff or Rdway	\$	
11	Ft. 1 in.	} Copper	} Pipe at	\$	
					C.I.
					C.I.
	Nipples	in. at		\$	
	Bushings	to in. at		\$	
	Red'g	} Coupl'gs	to in. at	\$	
	Inc'g				
	Union	in. at		\$	
	Meter	in. at		\$	
	Lead Joints	at		\$	
	Compound Joints	at		\$	
	Maintenance Foreman			\$	
	Hrs. Water Maint. Man-1	at		\$	
	Hrs. Water Maint. Man-2	at		\$	
	Hrs. Garage Foreman	at		\$	
	Hrs. Labor	at		\$	
	Hrs. Compressor	at		\$	
	Compensation Ins. at \$	per C		\$	
	Trucking			\$	
	Pav't Patch			\$	
	Tap Put Back in			\$	
	Service by Domo Kant			\$	
	O'head	11-30-70,		\$	
				\$	
				\$	

St. Glen
 Pl. 341
 Ave. No. 341
 Name of Owner Was Bullard
Now Glens Falls Ins Co.
New Bldg.
 Labor and Mat'l. Report Nov. 30 1970

Go BY MEASUREMENTS FROM HYDRANTS
 See Note
 These Poles HAVE BEEN Electric
 Light 49' 2" 40' 6" Light Pole
 Electric Light Pole
 Curb Box

12" Main Elev. of Main at tap 5'

Gate at ● Gate at ●
 Shut off at curb 2-14-1972

● Curb Box
 1" Tap
 made Apr. 24-87,
 Measured from 1st
 Eli Pole North of Pine
 St. on Glen St.
 Pine St.