

Labor and Materials

1	Copper } Connection	3	\$ 2.70
	Curb { Cock	4	\$ 2.39
	{ V. } in.	4	
	Service Box { Steel 3 1/2 x 4 1/2		\$ 1.55
	Old returned { Long 4 1/2 x 5 1/2		
	{ Butt on Railway }		
27	Ft. in. { Copper	3	\$ 7.83
	{ Galv. Iron } Pipe at	4	
	{ Cast Iron }		
	Nipples in. at		\$
	Bushings to in. at		\$
	Red'g } Couplings to in. at		\$
	Inc'g }		
	Union in. at		\$
	Meter in. at		\$
	Lbs. Br. Stone at		\$
	Lbs. Sand at		\$
	Bags Cement at		\$
	Paving Brick { Mack } at		\$
	{ Red }		
	{ Asphalt }		
	Lead Joints at		\$
	Leadite Joints at		\$
5	Hrs. Foreman at		\$ 5.-
35	Hrs. Common Labor at		\$ 15.75
	Hrs. Common Labor at		\$
	Hrs. Mason at		\$
	Hrs. Mason's Helper at		\$
2	Hrs. Compressor at		\$ 3.-
	Compensation Ins.		\$.63
	Trucking		\$ 1.-
	Builders' Use of Water <i>Perch</i>		\$ 25.-
	Total \$		69.85

30-29 390
 Labor and Material Report *Alpa* 24 1930

234 *Alpa*



12 Main Eley of Main at tap 4
 Gate at ● Gate at ●

Church Property ● Curb Box
*Ad Tap taken
 dug up.
 This house razed
 1961-62
 Shut off at Curb.*