

LABOR AND MATERIALS

1	Copper } Connection	3/4"	\$	
1	Curb } Cock	3/4 in.	\$	
	Valve } T.S. & V.			
1	Service box } Short 3-1/2 x 4-1/2		\$	
	Old returned } Long 4-1/2 x 5-1/2			
25	Ft. 3/4 in. } Copper	Pipe at	\$	
	Galv. } Galv.			
	Nipples	in. at	\$	
	Bushings	to in. at	\$	
	Red'g			
	Inc'g			
	Union	in. at	\$	
	Meter	in. at	\$	
			\$	
	Compound Joints at		\$	
	Maintenance Foreman		\$	
	Hrs. Water Maint. Man - 1 at		\$	
	Hrs. Water Maint. Man - 2 at		\$	
	Hrs. Garage Foreman	at	\$	
	Hrs. Labor	at	\$	
	Hrs. Compressor at		\$	
			\$	
	Trucking		\$	
	Pav't Patch		\$	
			\$	
			\$	
			\$	
			\$	

GRANT

St. Ave. No. 85

Name of Owner

Labor and Mat'l. Report 19 28 NOV. 6

NO MEASUREMENTS

● Curb Box

6" Main

Elev. of Main at tap 4 1/2'

● Gate at

● Gate at

● Curb Box