

Labor and Materials

1	Copper	Connection	3/4	\$	2.60
1	Curb	Cock	3/4 in.	\$	2.27
1	Service Box	Short 3 1/2 x 4 1/2		\$	1.38
	Old returned	Long 3 1/2 x 4 1/2		\$	
26	Pt.	3/4 in. Copper	Pipe at 3/4	\$	4.68
		in. at		\$	
	Nipples	in. at		\$	
	Bushings	to in. at		\$	
	Red'g	Couplings	to in. at	\$	
	Inc'g			\$	
	Union	in. at		\$	
	Meter	in. at		\$	
	Lbs. Br. Stone	at		\$	
	Lbs. Sand	at		\$	
	Bags Cement	at		\$	
	Paving Brick	Mack Red Asphalt at		\$	
	Lead Joints	at		\$	
	Leadite Joints	at		\$	
3	Hrs. Foreman	at		\$	1.88
4	Hrs. Common Labor	at		\$	1.80
	Hrs. Common Labor	at		\$	
	Hrs. Mason	at		\$	
	Hrs. Mason's Helper	at		\$	
	Hrs. Compressor	at		\$	
	Compensation Ins			\$.12
	Trucking			\$	1.00
	Builders' Use of Water	M. Patah		\$	0.00
				Total \$	75.73

Labor and Material Report

Oct 5 1931

95 GRANT AVE



Curb Box

6 11 Main

Elev of Main at tap

5'

Gate at ●

● Gate at

● Curb Box