

LABOR AND MATERIALS

1	Copper } Connection	3/4"	\$	_____
1	Curb } Cock Valve	3/4" in.	\$	_____
1	Service box	{ Short 3-1/2 x 4-1/2 }	\$	_____
	Old returned	{ Long 4-1/2 x 5-1/2 }	\$	_____
28	Ft. 3/4 in. { Copper }	Pipe at	\$	_____
_____	Nipples	_____ in. at	\$	_____
_____	Bushings	_____ to _____ in. at	\$	_____
_____	Red'g		\$	_____
_____	Inc'g		\$	_____
_____	Union	_____ in. at	\$	_____
_____	Meter	_____ in. at	\$	_____
_____	Compound Joints at		\$	_____
_____	Maintenance Foreman		\$	_____
_____	Hrs. Water Maint. Man - 1 at		\$	_____
_____	Hrs. Water Maint. Man - 2 at		\$	_____
_____	Hrs. Garage Foreman	_____ at	\$	_____
_____	Hrs. Labor	_____ at	\$	_____
_____	Hrs. Compressor at		\$	_____
_____	Trucking		\$	_____
_____	Pav't Patch		\$	_____
_____			\$	_____
_____			\$	_____
_____			\$	_____
_____			\$	_____
_____			\$	_____

GRANT St. Ave. No. 105
 Name of Owner _____

Labor and Mat'l. Report 19 35 Oct. 28

