

Labor and Materials

| | | | | | |
|---|-----------------------|------|---------------------|-----------|----|
| | Copper | Lead | Connection | | \$ |
| 1 | | | | | |
| 1 | Curb | | Cock Valve | in | \$ |
| | | | T. S. & V. | | |
| 1 | Service Box | | Short 3 1/2 x 4 1/2 | | \$ |
| | Old returned | | Long 4 1/2 x 5 1/2 | | |
| | | | Buff. or Rdway | | |
| 8 | Ft. | 3/4 | in. | Copper | \$ |
| | | | | Galv Iron | \$ |
| | | | | Cast Iron | \$ |
| | Nipples | | in. at | | \$ |
| | Bushings | | to | in. at | \$ |
| | Red'g | | to | in. at | \$ |
| | Inc'g | | to | in. at | \$ |
| | Union | | in. at | | \$ |
| | Meter | | in. at | | \$ |
| | Lead Joints | | at | | \$ |
| | Leadite Joints | | at | | \$ |
| | Hrs. Foreman | | at | | \$ |
| | Hrs. Chauffeur | | at | | \$ |
| | Hrs. Tapper | | at | | \$ |
| | Hrs. Labor | | at | | \$ |
| | Hrs. Labor | | at | | \$ |
| | Hrs. Compressor | | at | | \$ |
| | Compensation Ins. | | | | \$ |
| | Trucking | | | | \$ |
| | Builders Use of Water | | | | \$ |
| | | | | | \$ |
| | | | | | \$ |
| | | | | | \$ |
| | | | | | \$ |
| | | | | | \$ |
| | | | | | \$ |
| | | | | | \$ |

St. 467
 Pl. _____
 Ave. No. 277

Name of Owner
Mrs. A. M. Baker

Labor and Mat'l. Report 6/30/70 19

467

16" Main
Elev. of Main at tap 4 1/2

Gate at ● ● Gate at

● Curb Box

45' 0" 39' 6" 43' 1"
 16" main 4.5" elev