

LABOR AND MATERIALS

Copper	}	Connection	-----	\$	
Lead			-----	\$	
Curb	{	Cock Valve	-----	\$	
		T. S. & V.	-----	\$	
			in. -----	\$	
Service Box	{	Short 3 1/2 x 4 1/2	-----	\$	
Old returned		Long 4 1/2 x 5 1/2			
		Buff. or Rdway			
Ft. -----	}	Copper	Pipe at -----	\$	
in. -----		Galv Iron			
		Cast Iron			
Nipples -----	in. at -----	\$			
Bushings -----	to -----	in. at -----	\$		
Red'g Inc'g	}	Couplings -----	to -----	in. at -----	\$
Union -----	in. at -----	\$			
Meter -----	in. at -----	\$			
Lead Joints at -----	\$				
Leadite Joints at -----	\$				
Hrs. Foreman at -----	\$				
Hrs. Chauffeur at -----	\$				
Hrs. Tapper at -----	\$				
Hrs. Labor at -----	\$				
Hrs. Labor at -----	\$				
Hrs. Compressor at -----	\$				
Compensation Ins. -----	\$				
Trucking -----	\$				
Builders Use of Water -----	\$				
-----	\$				
-----	\$				
-----	\$				
-----	\$				
-----	\$				

St. Glen
 Ave. No. 32 1/2

Name of Owner
D.W. Fitzgerald, Jr.

Labor and Mat'l. Report MAY 9 1916

4" Main Oakland St. Elev. of Main at tap -----

Gate at ● ----- Gate at ● -----

● Curb Box