

LABOR AND MATERIALS

1	Copper	} Connection	1 1/4"	\$
	Lead			
1	Curb	} 1 1/4" Oriseal.		\$
			Cock	
			Valve - T. S. & V.	
1	Service box	} Oriseal.	Short 3 1/2 x 4 1/2	
	Old returned		Long 4 1/2 x 5 1/2	
			Buff or Rdway	\$ Box.
3	Ft. 1 1/4 in.	} Pipe at		\$
			Copper	
			G. I. / C. I.	
1	Nipples 1 1/4 in.		at	\$
	Bushings		to in. at	\$
	Red'g			
	Inc'g	Coupl'gs	to in. at	\$
	Union		in. at	\$
	Meter		in. at	\$
	Lead Joints		at	\$
	Compound Joints		at	\$
	Maintenance Foreman			\$
	Hrs. Water Maint. Man-1		at	\$
	Hrs. Water Maint. Man-2		at	\$
	Hrs. Garage Foreman		at	\$
	Hrs. Labor		at	\$
	Hrs. Compressor		at	\$
	Compensation Ins. at \$		per C	\$
	Trucking			\$
	Pav't Patch			\$
	Tap by Larcour & Co.			\$
			3-12-69	\$
	O'head			\$

St. 197
Pl. _____
Ave. No. 193

Glen

Name of Owner
Krusger-Jupiter

Labor and Mat'l. Report Mar. 12 19 69

12" Main

Elev. of Main at tap 5'

Gate at • Gate at •

3' to main

• Curb Box

Replaces 2" T.S. & V. Old 2" galv. pipe used as sleeve for 1 1/4"

LSM-5C-6-1-67

30.50
1.23
33.00

Labor and Materials

Copper	Connection		
Lead			
Curb	Cock Valve T. S. & V.	12x2"	33.00
Service Box	Short 3 1/2 x 4 1/2	Gate box	8.30
Old returned	Long 4 1/2 x 5 1/2		
	Buff. or Rdway		
Ft. 2	Copper Galv. Iron	Pipe at	3.33
Nipples	in. at		
Bushings	to in. at		
Red'g	Couplings	to in. at	
Union	in. at		
Meter	in. at		
lbs. Br. Stone	at		
lbs. Sand	at		
bags Cement	at		
Laying Brick	(Mack Red Asphalt)	at	
Lead Joints	at		
Leadite Joints	at		
rs. Foreman	at		9.35
rs. Common Labor	at		13.80
rs. Common Labor	at		
rs. Mason	at		
rs. Mason's Helper	at		
rs. Compressor	at		3.00
Compensation Ins.			82
Trucking			1.00
Builders' Use of Water			5.00
Total			72.0
12" joints			1.20

187-193

Labor and Material Report

19

129-131

Hydt.

12" 8" Q

187-193

● Curb Box

Gate box removed when new tap

Main Elev. of Main at tap

Gate at ● was made ● Gate at

● Curb Box

12"

Replace with 1 1/4" Copper Tap

Used 2" Galv pipe for sleeve for new Copper pipe

Mar 12-69