

Labor and Materials		
1	Lead Connection	\$
1	Curb-Cock	\$
	Service Box { Short 3 1/2 x 4 1/2	\$
	Old returned { Long 4 1/2 x 5 1/2	\$
	Buffalo	\$
5 1/2	Ft. in. G. I. Pipe at	\$
	Nipples in. at	\$
	Bushings to in. at	\$
	Red'g Coup to in. at	\$
	Inc'g Coup to in. at	\$
	Union in. at	\$
	Meter in. at	\$
	Cu. Yds. Br. Stone at	\$
	Cu. Yds. Sand at	\$
	Bags Cement at	\$
	Paving Brick { Mack	\$
	{ Red	\$
	{ Asphalt } at	\$
9	Hrs. Foreman at	\$
3.6	Hrs. Common Labor at	\$
	Hrs. Mason at	\$
	Hrs. at	\$
	Hrs. at	\$
2.5	Builders' Use of Water	\$
	at	\$
	Truck use	\$
	at	\$
	at	\$
	at	\$
	Total	\$

222 220
 Labor and Material Report Nov 28 1903

1" tap at 150' elevation

This place Razed

222-224

12" Main

Elev. of Main at tap

Gate at ● Gate at ●

● Curb Box

● Curb Box

Shut off at gate box
 Near 12" main.

This placed razed

12" main 4 ft Elev