	St.
GLEN	No. 228-232
Name of Owner	
	18 - 10592
Labor and Mat'l. Report 19	29, MAY 20
416"	209"
	Curb Box
	Elev. of Main at tap 53
Gate at	Gate at
200	
	Curb Box
No. 30	i)

LABOR AND MATERIALS

	IIIALO
Copper Connection	\$
J-4-56-V-	\$
Old returned Shert 3 1/2 x 4 1/2 Conditions of the service box Shert 3 1/2 Con	\$
39 Ft. / '' in. {Copper } Pipe at _	\$
Nipples in, at	\$
Bushings to in. at	
Red'g	
Inc'g	
Union in. at	\$
Meter in. at	
Compound Joints at	
Maintenance Foreman	s
Hrs. Water Maint. Man - 1 at	\$
Hrs. Water Maint. Man - 2 at	\$
Hrs. Garage Foreman at	
Hrs. Labor at	\$
Hrs. Compressor at	
Trucking	
Pav't Patch	_ \$
((
	\$