

LABOR AND MATERIALS

Copper	} Connection	_____	\$	
Lead		_____	\$	
Curb	} T. S. & V. }	_____ in.	\$	
		Cock	_____	\$
		Valve	_____	\$
Service box	} { Short 3½ x 4½ } Long 4½ x 5½ } Buff or Rdway }	_____	\$	
Old returned		_____	\$	
		_____	\$	
Ft. _____ in.	} { Copper } G. I. } C. I. }	Pipe at _____	\$	
Nipples _____ in.		at _____	\$	
Bushings _____ to _____ in.		at _____	\$	
Red'g } Inc'g }	} Coupl'gs _____ to _____ in.	at _____	\$	
Union _____ in.		at _____	\$	
Meter _____ in.	at _____	\$		
Lead Joints _____	at _____	\$		
Compound Joints _____	at _____	\$		
Maintenance Foreman _____	at _____	\$		
Hrs. Water Maint. Man—1 _____	at _____	\$		
Hrs. Water Maint. Man—2 _____	at _____	\$		
Hrs. Garage Foreman _____	at _____	\$		
Hrs. Labor— _____	at _____	\$		
Hrs. Compressor _____	at _____	\$		
Compensation Ins. at \$ _____	per C _____	\$		
Trucking _____		\$		
Pav't Patch _____		\$		
_____		\$		
_____		\$		
_____		\$		
O'head _____		\$		
_____		\$		

251 Glen St. St.
CRANDALL LIBRARY Pl.
 Ave. No. _____

Name of Owner

WATER TAP

Labor and Mat'l. Report

FRONT DOOR

FEB. 16 19 84



GLEN ST.

Main

Elev. of

Main at tap _____

Gate at ● _____

● Gate at _____

● Curb Box