

# LABOR AND MATERIALS

1	Copper	} Connection	3/4	\$
	Loss			
1	Curb	} Cock	3/4 in.	\$
1	Service box	{	Short 3-1/2 x 4-1/2	\$
	Old returned			
8	Ft.	} Copper	3/4 in.	\$
	Nipples		in. at	\$
	Bushings		to in. at	\$
	Red'g			
	Inc'g			
	Union		in. at	\$
	Meter		in. at	\$
				\$
	Compound Joints at			\$
	Maintenance Foreman			\$
	Hrs. Water Maint. Man - 1 at			\$
	Hrs. Water Maint. Man - 2 at			\$
	Hrs. Garage Foreman at			\$
	Hrs. Labor at			\$
	Hrs. Compressor at			\$
				\$
	Trucking			\$
	Pav't Patch			\$
				\$
				\$
				\$
				\$

St. GLEN Ave. No. 348

Name of Owner CHAPMAN MUSEUM

Labor and Mat'l. Report 1927, AUG 4



46'5"                      23'6"

● Curb Box

6" Main

Elev. of Main at tap 5'

Gate at ●

● Gate at

TAP ON BACON

● Curb Box

OLD TAP SHUT OFF