

LABOR AND MATERIALS

Copper	Lead	Connection	-----	\$	
Curb	{	Cock Valve	-----	in.	\$
		T. S. & V.	-----		
Service Box	{	Short 3 1/2 x 4 1/2	-----		\$
Old returned		Long 4 1/2 x 5 1/2	-----		
		Buff. or Rdway	-----		
Ft.	{	in.	-----	Pipe at	\$
Nipples		in.	-----	at	\$
Bushings		to	-----	in.	at
Red'g	{	Couplings	-----	to	in.
Inc'g			-----	at	\$
Union		in.	-----	at	\$
Meter		in.	-----	at	\$
Lead Joints		at	-----		\$
Leadite Joints		at	-----		\$
Hrs. Foreman		at	-----		\$
Hrs. Chauffeur		at	-----		\$
Hrs. Tapper		at	-----		\$
Hrs. Labor		at	-----		\$
Hrs. Labor		at	-----		\$
Hrs. Compressor		at	-----		\$
Compensation		Ins.	-----		\$
Trucking			-----		\$
Builders Use of Water			-----		\$
			-----		\$
			-----		\$
			-----		\$
			-----		\$
			-----		\$

St. 364-370
 Pl. _____
 Ave. No. 228

Name of Owner _____

Labor and Mat'l. Report

RAZED

364-370

228

1914

Fountain

15.5

● Curb Box

Main

Elev. of Main at tap

● Gate at

● Gate at

● Curb Box