Labor and Materials

1	Lead Connection 1/2	$
1	Curb Cock 3/4	$
1	Service Box Old returned { ~~Short 3½ x 4½~~ Long 4½ x 5½ ~~Buffalo~~	$
7	Ft. 3/4 in. G. I. Pipe at	$
	Nipples ..... in. at	$
	Bushings ..... to ..... in. at	$
	Red'g Coup .... to .... in. at	$
	Inc'g Coup .... to .... in. at	$
	Union .... in. at	$
	Meter .... in. at	$
	Cu. Yds. Br. Stone at	$
	Cu. Yds. Sand at	$
	Bags Cement at	$
	Paving Brick { Mack Red Asphalt } at	$
2	Hrs. Foreman at	$
8	Hrs. Common Labor at	$
	Hrs. Mason at	$
	Hrs. at	$
	Hrs. at	$
90	Builders' Use of Water	$
	at	$
	Truck 100 at	$
	at	$
	at	$
	Total	$ 10.85

Labor and Material Report

Aug 29 1928

1/2 Ft. at Sherman Dr. (Bay) Detroit

370 228 Glen St

54' Curb Box 58' 11"

RAZED

Main

Elev. of Main at tap

Gate at

Gate at

Curb Box