

LABOR AND MATERIALS

Copper	} Connection	_____	\$	
Lead				
Curb	} Cock	_____ in.	\$	
				} Valve
Service box	} Short 3½ x 4½	_____	\$	
Old returned				Long 4½ x 5½
				Buff or Rdway
Ft. _____ in.	} Copper	} Pipe at _____	\$	
				} G. I.
Nipples _____ in.	at _____	\$		
Bushings _____ to _____ in.	at _____	\$		
Red'g } Inc'g	} Coupl'gs. _____ to _____ in.	at _____	\$	
Union _____ in.				
Meter _____ in.	at _____	\$		
Lead Joints at _____		\$		
Compound Joints at _____		\$		
Maintenance Foreman _____		\$		
Hrs. Water Maint. Man-1 at _____		\$		
Hrs. Water Maint. Man-2 at _____		\$		
Hrs. Garage Foreman _____ at _____		\$		
Hrs. Labor _____ at _____		\$		
Hrs. Compressor at _____		\$		
Compensation Ins. at \$ _____ per C.		\$		
Trucking _____		\$		
Pay't Patch _____		\$		
_____		\$		
_____		\$		
_____		\$		
_____		\$		
O'head _____		\$		
_____		\$		

Glen

St. _____
Pl. _____
Ave. No. 366

Name of Owner

Filling Station

Measured

Labor and Mat'l. Report

may 6 1960



Main

Elev. of Main at tap _____

Gate at •

• Gate at

• Curb Box

This place measured
from 368 Glen St.
old or 370
Gas Station Get it water
from Ernst House Cobb
Tap