

LABOR AND MATERIALS

1	Copper } Connection $\frac{3}{4}$	\$
	Lead- } Cock	
1	Curb } Valve } $\frac{3}{4}$ in.	\$
1	Service box { Short 2-1/2 x 4-1/2 }	\$
	Old returned { Long 4-1/2 x 5-1/2 }	
14	Ft. $\frac{3}{4}$ in. { Copper } Pipe at	\$
	Nipples _____ in. at	\$
	Bushings _____ to _____ in. at	\$
	Red'g	
	Inc'g	
	Union _____ in. at	\$
	Meter _____ in. at	\$
		\$
	Compound Joints at	\$
	Maintenance Foreman	\$
	Hrs. Water Maint. Man - 1 at	\$
	Hrs. Water Maint. Man - 2 at	\$
	Hrs. Garage Foreman _____ at	\$
	Hrs. Labor _____ at	\$
	Hrs. Compressor at	\$
		\$
	Trucking	\$
	Pav't Patch	\$
		\$
		\$
		\$
		\$
		\$
		\$

GLEN

St.

Bl.

Ass. No. 397-399

Name of Owner

Labor and Mat'l. Report 1931, SEPT. 19



28-8

23-8

● Curb Box

12" Main

Elev. of Main at tap $\frac{4}{2}$ '

Gate at ●

● Gate at

● Curb Box

OLD SHUT OFF AT MAIN