

LABOR AND MATERIALS

Copper	} Connection	_____	\$ _____		
Lead					
Curb	} Cock } Valve } T. S. & V.	} _____ in.	\$ _____		
				} Short 3½ x 4½	} _____
Service box					
Old returned			\$ _____		
Ft. 4	} Copper } G. I. } C. I.	} Pipe at _____	\$ _____		
in.					
Nipples	_____ in. at _____	\$ _____			
Bushings	_____ to _____ in. at _____	\$ _____			
Red'g	} Coupl'gs _____ to _____ in. at _____	\$ _____			
Inc'g					
Union	_____ in. at _____	\$ _____			
Meter	_____ in. at _____	\$ _____			
Compound Joints	at _____	\$ _____			
Maintenance Foreman	_____	\$ _____			
Hrs. Water Maint. Man-1	at _____	\$ _____			
Hrs. Water Maint. Man-2	at _____	\$ _____			
Hrs. Garage Foreman	at _____	\$ _____			
Hrs. Labor	at _____	\$ _____			
Hrs. Compressor	at _____	\$ _____			
Trucking	_____	\$ _____			
Pav't Patch	_____	\$ _____			
		\$ _____			
		\$ _____			
		\$ _____			
		\$ _____			
		\$ _____			

GLENS FALLS TECHNICAL PK.

~~Industrial Park~~ St. Pl. Ave. No. 4

Name of Owner

Canavan

Labor and Mat'l. Report

19 86

