

LABOR AND MATERIALS

1	Copper } Connection	$\frac{3}{4}$	\$	_____
1	Curb } Cock	$\frac{3}{4}$ in.	\$	_____
	Value			
1	Service box	Short 3-1/2 x 4-1/2	\$	_____
	Old returned	Long 4-1/2 x 5-1/2	\$	_____
26	Ft. $\frac{3}{4}$ in. } Copper	Pipe at	\$	_____
	Nipples	_____ in. at	\$	_____
	Bushings	_____ to _____ in. at	\$	_____
	Red'g			_____
	Inc'g			_____
	Union	_____ in. at	\$	_____
	Meter	_____ in. at	\$	_____
			\$	_____
	Compound Joints at		\$	_____
	Maintenance Foreman		\$	_____
	Hrs. Water Maint. Man - 1 at		\$	_____
	Hrs. Water Maint. Man - 2 at		\$	_____
	Hrs. Garage Foreman	_____ at	\$	_____
	Hrs. Labor	_____ at	\$	_____
	Hrs. Compressor at		\$	_____
			\$	_____
	Trucking		\$	_____
	Pav't Patch		\$	_____
			\$	_____
			\$	_____
			\$	_____
			\$	_____
			\$	_____

St. GRAND Ave. No. 14
 Name of Owner _____
 TAX ID # 302.16-17-38

Labor and Mat'l. Report 19 26, Oct. 25



38'11" 28'2"

● Curb Box

4" Main (GALV.) Elev. of Main at tap 4'

Gate at ● Gate at ●

26' to main

● Curb Box